

Updated: 1/19/2024



Southern Ice


EQUIPMENT DISTRIBUTORS

Louisiana • Texas • Arizona • Arkansas • Mississippi • New Mexico

Closeout *and* Overstock List

*Please check with factory
for warranty

Harahan Equipment
5128 Storey St,
Harahan, LA 70123
504-734-5024

MAKE	MODEL	SERIAL NUMBER	DATE RECEIVED		ASKING PRICE
 RDI	PC249MZOP-3E (SCROLL, 2-1/2HP, MEDIUM TEMP, 208-230V, 3PH, R404A)	410066841	11/27/2013		








Closeout *and* Overstock List










Arkansas Equipment
8100 Scott Hamilton Dr., Ste A
Little Rock, AR 72209
501-569-9318

Updated: 1/19/2024

**Please check
with factory
for warranty*

MAKE	MODEL	SERIAL NUMBER	DATE RECEIVED		ASKING PRICE
	K-420 22" Ice Storage Bin scratch/dent on side of bin	1121023614			
	AUCS-SO-271 (AUTOMATIC CLEANING SYSTEM FOR S MODEL ICE MACHINE)	110657998	6/4/2012		
	IY0606A- Indigo Ice Machine - Half Dice, Air Cooled damaged, was nonoperational, has been repaired, no box	1120350575			
	EL16-36-2-PR-4 (LOW TEMP, 3,600 BTU, 1 FAN, 208-230V, R404A)	410021523	11/2/2010		
	KCBM23RSE-HC- 738100 Reach In Refrigerator	84213076	7/1/2019		

Houston Scratch *and* Dent List

MAKE	ITEM	DESCRIPTION	DAMAGE	SERIAL NUMBER	PRICE
	CR-UCM2-SW-2	(REMOTE TWO COIL CHILLER)		81160	
	KCCF073WS/738089)	Mobile Chest Freezer	slight damage	03922763	
	KCCF073WS/738089)		slight damage	03922757	
	738276/ KCHMC49	Milk Cooler	(2) small dents to front of unit, [(1) dent on door, which can be replaced]	2332037589	
	738244/ KCHRI271DFE	1-Door Freezer	Damage all-around the unit but can still operate, not sure if warranty will be available as the unit is badly damaged.	02921206	
	KCCF140WH/738230	Solid Top Chest Freezer 14 cu. ft.	Large dent broke through first wall on back left corner	13720025	
	KCCF140WH / 738230	CHEST FREEZER SOLID TOP 52" LONG	Unit works, pulls down to temp, lots of outside damage	2262000482	
	HPC7101-MSS1	Heated Proofer Cabinet	Dent on bottom left side, door does not correctly close when on right hinge, but is good on left hinge	17090181	
	Bromic Reflector BH3030001-1 Platinum 300 Series				



Phoenix Equipment
4202 E. Elwood, Ste. 15

Updated:
1/19/2024

**Closeout and
Overstock List**




Phoenix, AZ 85040 *Please check
602-470-2366 with factory for
warranty

MAKE	MODEL WITH DESCRIPTION	SERIAL NUMBER	DATE RECEIVED	ASKING PRICE	
RDI Systems	AM16-48-1-PR-4 (MEDIUM TEMP, 4,800 BTU, 1 FAN, 115V, R404A)	410081128	5/14/2014		
RDI Systems	AM36-170-1P-PR-4 (MEDIUM TEMP, 17,000 BTU, 3 FAN, 115V, R404A)	410138630	4/17/2017		
RDI Systems	PC249MZOP-3E (SCROLL, 2-1/2HP, MEDIUM TEMP, 208-230V, 3PH, R404A)	410066840	7/30/2013		

Phoenix Scratch *and* Dent List

Updated: 1/19/2024

*Please check with factory
for warranty

MAKE	MODEL	DESCRIPTION	DAMAGE	SERIAL NUMBER		ASKING PRICE
RDI Systems	PC99MZOP-3E		Call for Damage	410194018		
RDI Systems	PC149MOP-2E	208-230/60/1 Condensing Unit 1HP	Call for Damage	410135483		
RDI Systems	PC199LOP-2E	208-230/60/1 Condensing Unit 1HP	Fins Crushed on Lower Left Side of Condenser Coil	410098706		
 Kelvinator COMMERCIAL	KCUC27R 738024	Undercounter Refrigerator		IB51501279		
 Kelvinator COMMERCIAL	KCUC27R 738024	Undercounter Refrigerator		IB54501250		
 Kelvinator COMMERCIAL	KCUC27R-HC 738112	Undercounter Refrigerator		I81511517		