

Updated: 3/27/2024



**Lafayette Equipment**  
 112 Luke St., Lafayette, LA 70506  
 337-235-5813

Please check with factory

# Lafayette Scratch *and* Dent List

MAKE	MODEL	DESCRIPTION	DAMAGE	SERIAL NUMBER	ASKING PRICE
<b>Manitowoc</b>	D970	Ice Storage Bin - 882 lb.	The front of the bin has 3 small dings	1121025508	
<b>Kelvinator COMMERCIAL</b>	738265	27' c/ft --- Undercounter Freezer	Damage to front bottom kick panel is Heavy	14920249	



Updated: 3/27/2024

**Arkansas Equipment**  
 8100 Scott Hamilton Dr., Ste A  
 Little Rock, AR 72209  
 501-569-9318

\*Please check with factory for warranty

# Closeout *and* Overstock List

MAKE	MODEL	SERIAL NUMBER	DATE RECEIVED	ASKING PRICE
<b>Koolaire</b>	K-420 22" Ice Storage Bin	scratch/dent on side of bin	1121023614	
<b>Manitowoc</b>	AUCS-SO-271 ( AUTOMATIC CLEANING SYSTEM FOR S MODEL ICE MACHINE )		110657998	6/4/2012
<b>Manitowoc</b>	IY0606A- Indigo Ice Machine - Half Dice, Air Cooled	damaged, was nonoperational, has been repaired, no box	1120350575	
<b>RDI</b>	EL16-36-2-PR-4 ( LOW TEMP, 3,600 BTU, 1 FAN, 208-230V, R404A )		410021523	11/2/2010
<b>Kelvinator COMMERCIAL</b>	KCBM23RSE-HC- 738100	Reach In Refrigerator	84213076	7/1/2019



**Houston Equipment**  
**6835 Fulton Street,**  
**Houston, TX 77022**  
**713-742-9010**

**Updated: 3/27/2024**

*\*Please check with  
 factory for  
 warranty*

# Houston Scratch *and* Dent List

MAKE	ITEM	DESCRIPTION	DAMAGE	SERIAL NUMBER	PRICE
Kelvinator COMMERCIAL	KCUC27R/ 738024	Undercounter Refrigerator	No damage	IB51501279	
Kelvinator COMMERCIAL	KCUC27R/ 738024	Undercounter Refrigerator	No damage	IB54501250	
Kelvinator COMMERCIAL	KCUC27R-HC/ 738112	Undercounter Refrigerator	No damage	IB1511517	
Kelvinator COMMERCIAL	KCCF073WS/738089)	Mobile Chest Freezer	slight damage	03922763	
Kelvinator COMMERCIAL	KCCF073WS/738089)		slight damage	03922757	
Kelvinator COMMERCIAL	738276/ KCHMC49	Milk Cooler	(2) small dents to front of unit, [(1) dent on door, which can be replaced]	2332037589	
Kelvinator COMMERCIAL	KCCF140WH/738230	Solid Top Chest Freezer 14 cu. ft.	Large dent broke through first wall on back left corner	13720025	
Kelvinator COMMERCIAL	KCCF140WH / 738230	CHEST FREEZER SOLID TOP 52" LONG	Unit works, pulls down to temp, lots of outside damage	2262000482	
Kelvinator COMMERCIAL	KCST27.8-HC/ 738066	27" Prep Table	No damage	74113355	
Kelvinator COMMERCIAL	KCMT48.18-HC/ 738071	48" Megatop	No damage	83112331	
GOLOG	HPC7101-MSS1	Heated Proofer Cabinet	Dent on bottom left side, door does not correctly close when on right hinge, but is good on left hinge	17090181	
Crysalli Air-Ton Water	CR-UCM2-SW-2	( REMOTE TWO COIL CHILLER )		81160	
BROMIC HEATING	Bromic Reflector BH3030001-1 Platinum 300 Series				



Louisiana • Texas • Arizona • Arkansas • Mississippi • New Mexico

# Closeout and Overstock List

# Phoenix Equipment

## 4202 E. Elwood, Ste. 15

Updated:  
3/27/2024

# Phoenix, AZ 85040

## 602-470-2366

\*Please check with factory for warranty

MAKE	MODEL WITH DESCRIPTION	SERIAL NUMBER	DATE RECEIVED	ASKING PRICE
<b>RDI Systems</b>	AM16-48-1-PR-4 ( MEDIUM TEMP, 4,800 BTU, 1 FAN, 115V, R404A )	410081128	5/14/2014	
<b>RDI Systems</b>	AM36-170-1P-PR-4 ( MEDIUM TEMP, 17,000 BTU, 3 FAN, 115V, R404A )	410138630	4/17/2017	
<b>RDI Systems</b>	PC249MZOP-3E ( SCROLL, 2-1/2HP, MEDIUM TEMP, 208-230V, 3PH, R404A )	410066840	7/30/2013	

# Phoenix Scratch and Dent List

Updated: 3/27/2024

\*Please check with factory  
for warranty

MAKE	MODEL	DESCRIPTION	DAMAGE	SERIAL NUMBER	ASKING PRICE
<i>RDI Systems</i>	PC99MZOP-3E		Call for Damage	410194018	
<i>RDI Systems</i>	PC149MOP-2E	208-230/60/1 Condensing Unit 1HP	Call for Damage	410135483	
<i>RDI Systems</i>	PC199LOP-2E	208-230/60/1 Condensing Unit 1HP	Fins Crushed on Lower Left Side of Condenser Coil	410098706	