

Updated: 5/31/2024



Lafayette Equipment
 112 Luke St., Lafayette, LA 70506
 337-235-5813

Please check with factory

Lafayette Scratch *and* Dent List

MAKE	MODEL	DESCRIPTION	DAMAGE	SERIAL NUMBER	ASKING PRICE
Manitowoc	D970	Ice Storage Bin - 882 lb.	The front of the bin has 3 small dings	1121025508	
Kelvinator COMMERCIAL	738265	27' c/ft --- Undercounter Freezer	Damage to front bottom kick panel is Heavy	14920249	



Updated: 5/31/2024

























Arkansas Equipment
 8100 Scott Hamilton Dr., Ste A
 Little Rock, AR 72209
 501-569-9318

*Please check with factory for warranty

Closeout *and* Overstock List

MAKE	MODEL	SERIAL NUMBER	DATE RECEIVED	ASKING PRICE
Koolaire <small>by MANITOWOC</small>	K-420 22" Ice Storage Bin	scratch/dent on side of bin	1121023614	
Manitowoc	AUCS-SO-271 (AUTOMATIC CLEANING SYSTEM FOR S MODEL ICE MACHINE)		110657998	6/4/2012
RDI	EL16-36-2-PR-4 (LOW TEMP, 3,600 BTU, 1 FAN, 208-230V, R404A)		410021523	11/2/2010
Kelvinator COMMERCIAL	KCBM23RSE-HC- 738100	Reach In Refrigerator	84213076	7/1/2019

Houston Scratch *and* Dent List

MAKE	ITEM	DESCRIPTION	DAMAGE	SERIAL NUMBER	PRICE
 Kelvinator COMMERCIAL	KCUC27R/ 738024	Undercounter Refrigerator	No damage	IB51501279	
 Kelvinator COMMERCIAL	KCUC27R/ 738024	Undercounter Refrigerator	No damage	IB54501250	
 Kelvinator COMMERCIAL	KCUC27R-HC/ 738112	Undercounter Refrigerator	No damage	I81511517	
 Kelvinator COMMERCIAL	KCCF073WS/738089)	Mobile Chest Freezer	slight damage	03922763	
 Kelvinator COMMERCIAL	KCCF073WS/738089)	Mobile Chest Freezer	slight damage	03922757	
 Kelvinator COMMERCIAL	KCHMC49/738276/	Milk Cooler	(2) small dents to front of unit, [(1) dent on door, which can be replaced]	2332037589	
 Kelvinator COMMERCIAL	KCNF073WS/738090	Chest Freezer		4223693	
 Kelvinator COMMERCIAL	KCCF140WH/738230	Solid Top Chest Freezer 14 cu. ft.	Large dent broke through first wall on back left corner	13720025	
 Kelvinator COMMERCIAL	KCCF140WH / 738230	CHEST FREEZER SOLID TOP 52" LONG	Unit works, pulls down to temp, lots of outside damage	2262000482	
 Kelvinator COMMERCIAL	KCST27.8-HC/ 738066	27" Prep Table	No damage	74113355	
 Kelvinator COMMERCIAL	KCMT48.18-HC/ 738071	48" Megatop	No damage	83112331	
 Crysalli	CR-UCM2-SW-2	(REMOTE TWO COIL CHILLER)		81160	
 GOLOC	HPC7013HF	Insulated Cook and Hold Oven	no damage, was floor model, out of box	18030026	
 GOLOC	HPC7101-MSS1	Heated Proofer Cabinet	Dent on bottom left side, door does not correctly close when on right hinge, but is good on left hinge	17090181	
 BROMIC HEATING	Reflector BH3030001-1 Platinum 300 Series				
 DITO SAMA	600395	MultiGreen Food Processor/ Vegetable Slicer Food Processor	Unit was previously used as a demo. It is new but the box is rough	0061210009	
 DITO SAMA	600579	Food Processor		84710001	
 DITO SAMA	600579	Food Processor		85010001	
 DITO SAMA	600579	Food Processor		85010002	
 DITO SAMA	600575	Tomato Slicer		85110012	
 DITO SAMA	600575	Tomato Slicer		85110023	
 DITO SAMA	600575	Tomato Slicer		85110024	
 DITO SAMA	600575	Tomato Slicer		85110029	
 DITO SAMA	600575	Tomato Slicer		85110032	



Louisiana • Texas • Arizona • Arkansas • Mississippi • New Mexico

Closeout *and* Overstock List

Phoenix Equipment

4202 E. Elwood, Ste. 15

Updated:
5/31/2024

Phoenix, AZ 85040

602-470-2366

*Please check with factory for warranty

MAKE	MODEL WITH DESCRIPTION	SERIAL NUMBER	DATE RECEIVED	ASKING PRICE
RDI Systems	AM16-48-1-PR-4 (MEDIUM TEMP, 4,800 BTU, 1 FAN, 115V, R404A)	410081128	5/14/2014	
RDI Systems	AM36-170-1P-PR-4 (MEDIUM TEMP, 17,000 BTU, 3 FAN, 115V, R404A)	410138630	4/17/2017	
RDI Systems	PC249MZOP-3E (SCROLL, 2-1/2HP, MEDIUM TEMP, 208-230V, 3PH, R404A)	410066840	7/30/2013	

Phoenix Scratch and Dent List

Updated: 5/31/2024

*Please check with factory
for warranty

MAKE	MODEL	DESCRIPTION	DAMAGE	SERIAL NUMBER		ASKING PRICE
<i>RDI Systems</i>	PC99MZOP-3E		Call for Damage	410194018		
<i>RDI Systems</i>	PC149MOP-2E	208-230/60/1 Condensing Unit 1HP	Call for Damage	410135483		
<i>RDI Systems</i>	PC199LOP-2E	208-230/60/1 Condensing Unit 1HP	Fins Crushed on Lower Left Side of Condenser Coil	410098706		